APPENDIX III

Ref	Property	Floor Area	Condition	Urgent Work	Essential Work	Desirable Work
		m2	Category	£	£	£
13.01 Golf Clubhouse		430 Good		0	18917	25915
13.06 Garden Cottage		77 Poor		21400	10648	2519
13.11 Kios	13.11 Kiosk		8 Satisfactory	0	3210	1070
13.14 Stre	13.14 Stream Cottage No.2		0 Good	0	1855	2668
13.15 Stre	13.15 Stream Cottage No.3		100 Good		4717	2668
13.16 Stream Cottage No.4		100 Good		0	1855	2668
13.20 Golf Clubhouse Mess Room		99 Satisfactory		0	1070	1070
41.03 Public Conveniences		64 Good		0	5839	5896
Tota	al	98	8	21400	48111	44474

A Percentage of floor area in condition A-D

 Good
 80.36%

 Satisfactory
 11.84%

 Poor
 7.79%

B1 Cost of required maintenance as cost in priority levels 1-3

 Urgent
 £21,400

 Essential
 £48,111

 Desirable
 £44,474

B2 Cost of required maintenance as a percentage of cost in priority levels 1-3

 Urgent
 18.77%

 Essential
 42.21%

 Desirable
 39.02%

B3 Cost of required maintenance per square metre

£115.37 m2

C Annual percentage change to total required maintenance over previous year

2008/9 2007/8

Required maintenance 113985 92585
Change 23%

D1 Total spend on maintenance £

Planned maintenance 7816
Reactive maintenance 8696
Total 16512

D2 Total spend on maintenance per square metre

£16.71 per m2

D3 Percentage split of total spend on maintenance between planned and responsive maintenance

47% Planned 53% Responsive