

Date: 17-July-2023

Time: 12:35:51

Title: **Linton Crossroads**

Requested output: **D - Print Crash Report**

Date: 17-July-2023

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

There were 29 reported crashes resulting in injury

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
1	Road No B2163 Grid 575542E Section 166 Ref 150868N	SLIGHT	01/03/2015	1	20:13	DRK STL	Wet/Damp	Fine		R.TURN	
B2163, Heath Road Jw Linton Hill, Maidstone, Kent									Maidstone		
V1 was Travelling from Boughton Monchelsea and was Signalling to Turn right from the B2163 into A229 Towards Maidstone. V2 was Travelling Straight across the Junction from Heath Road into B2163. V1 Did Not See V2 and Crossed into Their Pathway. They Collided Causing Injury to the Driver of V1.							Veh1, car, E -> N Veh2, car, W -> E			Casualties 1 Vehicles 2	
2	Road No A229 Grid 575547E Section 168 Ref 150894N	SLIGHT	23/03/2015	2	11:30	L	Dry	Fine	N	S.VEH	PSV
A229, Linton Road, 30M North of B2163 Heath Road, Maidstone, Kent									Maidstone		PED
Pedestrian was Running for the Bus which Had Stopped at the Bus Stop, North Bound A229 Linton Road, as Ped Approached the Bus it Started to Pull Away from the Bus Stop Approx 30-40 Metres from the Jw Heath Road B2163. Ped Tried to Get the Bus Drivers Attention by Banging the Side of the Bus. as Ped was Doing So Lost Footing on the Kerb, Stumbled and Fell into the Road Between the Kerb and the Bus. the Bus Continued to Move Away for 2-3 Seconds Until the Driver Noticed Ped and Stopped.							Veh1, bus or coach, SW -> NE			Casualties 1 Vehicles 1	
3	Road No A229 Grid 575547E Section 168 Ref 150864N	SERIOUS	28/03/2015	7	13:00	L	Dry	Fine		R.TURN	M/C
A229 Linton Road Jw B2163 Heath Road, Maidstone, Kent									Maidstone		
V1 was turning right out of Heath Road, Coxheath into Linton Hill (Linton Crossroads). V2 was Travelling Along Heath Road Towards Coxheath. There was a Veh Blocking the View of V1. the Driver of V1 Has Manoeuvred Slowly but both Vehicles Have Collided. the Rider of V2 was Thrown off the Motorbike across the Junction. the Rider Had a Broken Ankle.							Veh1, car, W -> S Veh2, m/cycle 50 - 125cc, E -> W			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
4	Road No A229 Grid 575549E Section 168 Ref 150860N	SLIGHT	04/05/2015	2	07:40	L	Wet/Damp	Fine		R.TURN	
Linton Hill, North of Heath Road, Maidstone, Kent									Maidstone		
V1 was Approaching the Crossroads from Heath Road (Coxheath Direction). V1 was Supposed to Stop/Give Way at the Crossroads, Despite a Green Light, They Didnt and Continued. V1 Drove with the Intention of turning right Towards Staplehurst. on the Crossroads as They Made the Manoeuvre, V1 Saw the Driver of V2 Drive at Speed and then Felt the Collision. V1 Admitted to Fault Despite V2 Driving at Speed as V1 was Supposed to Give Way. Secas Called. Nothing Further - Section 170 Complied.							Veh1, car, W -> S Veh2, car, E -> W			Casualties 1 Vehicles 2	
5	Road No A229 Grid 575527E Section 167 Ref 150831N	SLIGHT	27/08/2015	5	11:30	L	Wet/Damp	Rain			
A229 Linton Hill, 50 Metres from Linton/Heath Road Crossroads, Maidstone, Kent									Maidstone		
Apparantly V2 was Stationary in Traffic when V1 Collided into the Rear of It.							Veh1, car, S -> N Veh2, car, S -> P			Casualties 1 Vehicles 2	
6	Road No A229 Grid 575544E Section 167 Ref 150826N	SERIOUS	28/09/2016	4	19:20	DRK STL	Dry	Fine			M/C
A229, LINTON HILL, LINTON (MAPPED TO 575544,150826)									Maidstone		
V1 TRAVELLING BEHIND V2 WHICH STOPPED IN TRAFFIC. V1 FAILED TO REALISE THIS AND RAN INTO THE BACK OF V2. RIDER OF V1 FELL OFF AND INJURED THEIR LEG. NO INJURIES TO OCCUPANTS OF V2.							Veh1, m/cycle 50 - 125cc, E -> W Veh2, car, W -> E			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
7	Road No A229 Grid 575535E Section 167 Ref 150829N	SLIGHT	05/11/2016	7	18:09	DRK STL	Dry	Fine		+VE	
A229, LINTON HILL, MAIDSTONE (MAPPED TO 575535,150829)									Maidstone		
V1 TRAVELLING TOWARDS MAIDSTONE, LINTON ROAD. V1 HAS DRIVEN INTO THE BACK OF V2 WHICH WAS STATIONARY AT THE TRAFFIC LIGHTS, IN TURN THIS HAS LED TO V2 SHUNTING INTO V3 WHICH WAS ALSO STATIONARY AT TRAFFIC LIGHTS, IT WAS MENTIONED AT THE TIME THAT D1 SMELLED OF ALCOHOL.							Veh1, car, SW -> NE Veh2, car, SW -> NE Veh3, car, SW -> NE			Casualties	1
										Vehicles	3
8	Road No A229 Grid 575534E Section 168 Ref 150862N	SLIGHT	16/11/2016	4	08:30	L	Dry	Fine		R.TURN	
A229, LINTON HILL, MAIDSTONE (MAPPED TO 575534,150862)									Maidstone		
V2 was at the traffic lights waiting to turn right into Heath Road. V1 came up behind V2 and did not stop in time. V1 hit V2. The driver of V1 said that they had a coughing fit so didn't stop in time.							Veh1, car, S -> N Veh2, car, S -> N			Casualties	1
										Vehicles	2
9	Road No B2163 Grid 575547E Section 168 Ref 150869N	SLIGHT	17/02/2017	6	20:00	DRK STL	Dry	Fine		R.TURN	M/C
B2163 HEATH ROAD, AT J/W A229 LINTON ROAD, LOOSE, MAIDSTONE									Maidstone		
V1 turning right into Linton Road towards Loose. V2 travelling along Heath Road towards Boughton Monchelsea. V1 turned across V2, knocking the rider off.							Veh1, car, E -> N Veh2, m/cycle 50 - 125cc, W -> E			Casualties	1
										Vehicles	2

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
10	Road No B2163 Grid 575533E Section 166 Ref 150867N	SLIGHT	19/03/2018	2	16:22	DRK NSL	Dry	Fine			
	B2163, HEATH RD J/W A229 LOOSE RD, BOUGHTON MONCHELSEA.									Maidstone	
V2 stationary at traffic lights. V1 collided with rear of V2. V1 failed to stop.							Veh1, car, W -> E Veh2, car, W -> E			Casualties	1
										Vehicles	2
11	Road No A229 Grid 575574E Section 169 Ref 150943N	SLIGHT	19/04/2018	5	07:30	L	Dry	Fine			P/C
	A229 LINTON RD O/S SHELL GARAGE, LOOSE (MAPPED TO DESC. ORIGINAL COORDS - 575585,151979)									Maidstone	
THE COLLISION HAPPENED AS THE ROAD NARROWS WITH A CENTRAL ISLAND AND SEPARATES INTO TWO LANES. V2 WAS ON THE OUTSIDE OF V1 WHO WAS MOVING VERY SLOWLY IN TRAFFIC. AS V1 HAS MOVED OVER IT HAS CLIPPED V2 WHO WAS UP BY THE TRACTOR UNIT AND UNSEEN BY THE D1 OF THE LEFT HAND DRIVE LORRY.							Veh1, agric veh, NE -> SW Veh2, pedal cycle, NE -> SW			Casualties	1
										Vehicles	2
12	Road No A229 Grid 575566E Section 169 Ref 150935N	SLIGHT	09/07/2018	2	21:14	DRK STL	Dry	Fine		R.TURN	M/C
	A229 LINTON RD J/W SHELL PETROL STATION, LOOSE (MAPPED TO DESC. ORIGINAL COORDS - 575567,151196)									Maidstone	
V1 was travelling south along Linton Rd and V2 was travelling in the opposite direction. V1 reached the give way junction to turn into the Shell petrol station. To enter the petrol station, V1 had to cross V2's path. V1 has not seen V2 and has pulled out in front of V2, causing a collision.							Veh1, car, NE -> NW Veh2, m/cycle > 500cc, SW -> NE			Casualties	2
										Vehicles	2

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
13	Road No A229 Grid 575572E Section 169 Ref 150953N	SLIGHT	25/10/2018	5	00:16	DRK STU	Wet/Damp	Fine		S.VEH	
A229, LINTON RD, OPPOSITE SHELL GARAGE, LINTON.									Maidstone		
V1 travelling out of Maidstone towards Linton Hill. The road was damp, D1 believes they may have hit kerb and lost control. D1 said vehicle is quite powerful and vehicle hit lamppost and wall, ending up on verge.							Veh1, car, NE -> SW			Casualties	1
										Vehicles	1
14	Road No A229 Grid 575552E Section 168 Ref 150867N	SERIOUS	25/12/2018	3	21:53	DRK STL	Wet/Damp	Rain			
A229 LINTON HILL CROSSROADS J/W B2163 HEATH ROAD, LINTON									Maidstone		
V1 was on urgent duty driving with lights and sirens in use responding to an emergency call. As it headed in the general direction of Linton along A229 Linton Road, it approached a set of traffic signals at the junction with B2163 Heath Road and proceeded through a red light as V2 was travelling along B2163 in the general direction of Boughton Monchelsea, having passed through a green light. V1 collided with the nearside of V2, causing V2 to leave the carriageway to the offside where it came to rest and V2 stopping in the middle of the junction facing towards Boughton Monchelsea.							Veh1, car, NE -> SW Veh2, car, W -> E			Casualties	3
										Vehicles	2
15	Road No A229 Grid 575550E Section 168 Ref 150859N	SERIOUS	17/01/2020	6	11:05	L	Dry	Fine		R.TURN	
A229 LINTON RD J/W B2163 HEATH RD, COXHEATH									Maidstone		
V2 was travelling west on Heath Rd and saw two vehicles, including V1, stationary in the middle of the junction, indicating to turn right onto Linton Hill. V1 then turned across the path of V2, causing V2 to collide with the nearside of V1.							Veh1, car, W -> SW Veh2, car, E -> W			Casualties	2
										Vehicles	2

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
16	Road No A229 Grid 57559E Section 168 Ref 150894N	SLIGHT	25/01/2020	7	21:52	DRK STL	Wet/Damp	Other			PSV
	A229 LINTON J/W B2163 HEATH RD, COXHEATH									Maidstone	
V2 was stationary at the traffic lights when V1 collided with its rear. V1 failed to stop at the scene and sped away.							Veh1, car, NE -> SW Veh2, bus or coach, NE -> SW			Casualties 1 Vehicles 2	
17	Road No B2163 Grid 57552E Section Ref 150860N	SLIGHT	24/04/2020	6	19:53	DRK STL	Dry	Fine		R.TURN	PSV
	B2163 HEATH RD J/W A229 LINTON HILL, LINTON. (MAPPED TO NEW GRIDS, ORIGINAL GRIDS 575530, 150829)									Maidstone	
Both cars were coming from opposite directions. V2 was going straight over the crossroads and V1 was turning right. They both thought they had right of way so continued driving. This caused a head on collision between the two vehicles. Both cars were left undriveable. Driver of V2 was taken to hospital as they had a large lump on their forehead as a result of the collision.							Veh1, car, W -> S Veh2, car, E -> W			Casualties 1 Vehicles 2	
18	Road No B2163 Grid 575541E Section 166 Ref 150865N	SLIGHT	04/08/2020	3	13:57	L	Dry	Fine		R.TURN	PSV
	B2163 HEATH RD J/W A229 LINTON RD, COXHEATH									Maidstone	
V1 was travelling eastbound on Heath Road approaching Linton crossroads. Driver of V1 misjudged the right lane onto Linton Hill and swerved to avoid V2. V1 then veered onto the automatic traffic signal on the north bound approach to the crossroads on Linton Hill. Driver of V1 has admitted this was a error of judgement. The passenger has medical history and was seen by Secas at scene, prior to being taken to Pembury Hospital.							Veh1, car, W -> S Veh2, car, E -> S			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
19	Road No A229 Grid 575535E Section 168 Ref 150849N	SERIOUS	17/09/2020	5	08:36	L	Dry	Fine	E	S.VEH	
A229, LINTON HILL J/W B2163 HEATH RD, LINTON.									Maidstone	PED	
The casualty was on foot waiting to cross the road at the traffic lights. The traffic turning left towards Coxheath was stationary although the traffic lights were green. The casualty could not see any cars in lane two and crossed the road. A car in lane two collided with the casualty.							Veh1, car, S -> NE			Casualties	1
										Vehicles	1
20	Road No A229 Grid 575543E Section 168 Ref 150864N	SLIGHT	30/09/2020	4	11:50	L	Dry	Fine		R.TURN	
A229, LINTON RD J/W B2163 HEATH RD, LINTON.									Maidstone		
V1 has been waiting in crossroads, as V2 has approached V1 has flashed main beam in signal to continue. As V2 has gone to pass V1 on offside, V1 has turned and vehicles have collided. V1 was immobilized and V2 was able to clear junction and park nearby. Driver returned to scene.							Veh1, car, W -> S Veh2, car, E -> W			Casualties	2
										Vehicles	2
21	Road No B2163 Grid 575570E Section 166 Ref 150861N	SLIGHT	06/11/2020	6	08:18	L	Wet/Damp	Other			
B2163 HEATH RD J/W A229 LINTON RD, MAIDSTONE									Maidstone		
V2 and V3 were travelling west on Heath Rd and came to a stop at the traffic lights. V1 failed to stop in time and collided with the rear of V2, shunting it into the rear of V3.							Veh1, car, E -> W Veh2, car, E -> W Veh3, car, E -> W			Casualties	1
										Vehicles	3

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
22	Road No A229 Grid 575546E Section 168 Ref 150866N	SLIGHT	04/01/2021	2	14:38	L	Wet/Damp	Fine		R.TURN	
A229, LINTON RD J/W B2163 HEATH RD, COXHEATH.									Maidstone		
V2 was travelling along Heath Rd, when they came to the crossroad with A229. Traffic lights were green so proceeded through the traffic lights intending to go straight ahead towards Boughton Monchelsea. When V2 proceeded through the lights it collided with V1 who was sat in the filter lane to turn right onto A229 to go towards Maidstone.							Veh1, car, E -> N Veh2, car, W -> E			Casualties 2 Vehicles 2	
23	Road No A229 Grid 575549E Section 168 Ref 150859N	SLIGHT	09/05/2021	1	16:32	L	Dry	Fine		R.TURN	
A229 LINTON RD J/W B2163 HEATH RD, COXHEATH									Maidstone		
V1 WAS TRAVELLING EAST ON HEATH RD AND TURNED RIGHT TOWARDS LINTON HILL ACROSS THE PATH OF V2 AND CAUSED A HEAD ON COLLISION.							Veh1, car, W -> SW Veh2, car, E -> W			Casualties 1 Vehicles 2	
24	Road No A229 Grid 575547E Section 168 Ref 150878N	SLIGHT	06/10/2021	4	08:23	L	Dry	Other	SE	S.VEH	GV
A229 LINTON RD J/W B2163 HEATH RD, COXHEATH									Maidstone		PED
C1 was crossing Linton Rd in an easterly direction and had the right of way at the pedestrian crossing. V1, travelling southwest on Linton Rd, failed to stop at the lights and collided with C1 before driving off.							Veh1, goods < 3.5t, SW -> NE			Casualties 1 Vehicles 1	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
25	Road No B2163 Grid 575488E Section 034 Ref 150867N	SLIGHT	07/10/2021	5	08:30	L	Dry	Fine	E	S.VEH	GV
B2163 HEATH RD, COXHEATH (MAPPED TO COORDS)									Maidstone	PED	
C1 was walking in an easterly direction on Heath Rd when V1 approached from behind, mounted the pavement and collided with C1. V1 did not stop at the scene.							Veh1, goods < 3.5t, W -> E			Casualties	1
										Vehicles	1
26	Road No A229 Grid 575543E Section Ref 150862N	SLIGHT	20/12/2021	2	12:00	L	Dry	Fine		R.TURN	
A229, LINTON RD J/W B2163 HEATH RD, LINTON.									Maidstone		
V1 travelling along Heath Rd towards Linton crossroads, V1 committed through the lights and collided with V2. V2 was preparing to turn right from Linton Rd towards Coxheath, upon edging out V1 collided with the front of V2 causing extensive damage.							Veh1, car, E -> W Veh2, car, N -> W			Casualties	1
										Vehicles	2
27	Road No A229 Grid 575558E Section Ref 150881N	SLIGHT	02/03/2022	4	08:20	L	Dry	Fine	SE	S.VEH	
A229 LINTON RD J/W B2163 HEATH RD, LOOSE									Maidstone	PED	
C1 was crossing the road at the pedestrian crossing when the traffic lights changed to green for oncoming traffic. C1 was then struck by V1, which was travelling southwest on Linton Rd, at low speed before their foot was run over. V1 did not stop at the scene.							Veh1, car, NE -> SW			Casualties	1
										Vehicles	1

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

17-Jul-2023

12:35:51

Linton Crossroads

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2022'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
28	Road No A229 Grid 575535E Section 168 Ref 150841N	SLIGHT	28/09/2022	4	22:00	DRK STL	Dry	Fine		S.VEH	PSV
A229 LINTON HILL J/W HEATH ROAD, LINTON									Maidstone		
FROM OLR: D1 DRIVING BUS TOWARDS COXHEATH. THEY HAD TO BRAKE HARSHLY AT THE TRAFFIC LIGHTS AND C1 PASSENGER BANGED THEIR HEAD ON THE RAIL. THEY DID NOT TELL D1 UNTIL THEY GOT OFF AND JUST SAID 'I BANGED MY HEAD' AND LEFT THE BUS WITHOUT GIVING THEIR DETAILS. THEY JUST SAID NOT TO WORRY ABOUT IT. (DETAILS UNKNOWN FOR C1)							Veh1, bus or coach, SW -> NE			Casualties 1 Vehicles 1	
29	Road No A229 Grid 575554E Section 168 Ref 150868N	SLIGHT	01/12/2022	5	21:17	DRK STL	Wet/Damp	Rain			HGV
A229, LINTON RD J/W B2163 HEATH RD, LOOSE.									Maidstone		
AMBULANCE ON BLUE LIGHTS HAS SLOWLY GONE THROUGH A RED LIGHT TRAVELLING FROM MAIDSTONE TOWARDS STAPLEHURST. V1 HAS BEEN TRAVELLING FROM COXHEATH TOWARDS BOUGHTON MONCHELSEA AND HAS TRAVELLED THROUGH A GREEN LIGHT NOT SEEING AMBULANCE UNTIL COLLIDING WITH OFFSIDE.							Veh1, car, W -> E Veh2, goods 3.5 - 7.5t, N -> S			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective