

Appendix C – Street Lighting

Appendix C1

Structural testing has now been completed. We have now identified 316 failures, in the Maidstone area. KCC intend to replace all columns that have failed. However this is an ongoing programme, therefore a further update will be supplied to the board, on Wednesday 23rd January 2013. Please see below information outlining the columns that have failed within that ward identified.

Ward	Number of columns failed
Allington	31
Bearsted	5
Boxley	87
Bridge	17
Coxheath	7
East	19
Fant	18
Harrietsham & Lenham	1
Heath	7
High Street	63
North	11
North Downs	2
Park Wood	16
Shepway South	13
South	13
Staplehurst	6

Contact officer: Richard Emmett/Carol Valentine

Tel: 08458 247800